

IMPORTANT SAFETY ALERT

2013 DIAMONDBACK STEILACOOM RCX BICYCLES sold from August 2012 - September 2012



Bicycles may have been assembled with the incorrect headset parts that could cause the steerer tube to fail, causing the rider to lose control and fall or crash. Consumers should stop riding their bicycle and take it to an authorized Diamondback dealer to have it inspected.

Bicycles found to have the incorrect headset parts will have the fork replaced and assembled with the correct headset parts at no charge.

Please contact us at **(800) 222-5527** from 8 a.m. to 4 p.m. PT
Monday through Friday, if you have any questions.
DIAMONDBACK BICYCLES 6004 S. 190th Street, Suite 101, Kent WA 98032